"texture with one piece completely isolated on the left bottom and a bent piece on the top right unable to flatten it completely also with one piece falling slightly on the left having to fill quite some gap"

"setting up this texture with some bent pieces and suddenly getting my welder stuck identifying the problem only after taking my time dismantling the tip of my gun and cleaning it resuming the welding with two small pieces poorly connected at the bottom"

"not so many issues welding this texture with only a long piece with some rust hard to go through and a small piece at the bottom left poorly connected"

"sturdy texture using a bent piece in the middle making a bit problematic especially in one corner overlapping with a lower piece and having to grind a bit of the latter"

"welding after dinner and feeling concerned about the fumes now that my neighbour had me to move the fan feeling it is not as powerful as before seating at the opposite end and nonetheless making a fairly strong texture with only a piece on the top left poorly connected"

"making a sturdy texture despite the many bent pieces and only after finishing realizing that one of them got too much to the right but this time accepting the mistake i the end however going back to it and breaking the texture apart to weld it properly causing however quite a gap to the side"

"welding with an extra filter in my mouth for a better protection from the fumes and waking up in the middle of the night to update my project and make textures with still dark outside and rain and cold nonetheless managing pretty well with a pattern connected well by a long piece at the bottom"

"a bit problematic to set up this texture going out like a spider but in the end managing quite well also making up an interesting shape all well connected"

"another sturdy texture just making a bit of a mess initially trying to lift it to get a piece that has fallen behind it and breaking the pieces i already place on top with dots of weld"

"having to hammer down a bent piece after welding it on the opposite side but managing well and in the end resulting in a sturdy texture on the right with a small and a big poorly connected part on the left"

"pursuing welding despite having troubles breathing with the mask packed with filters and making a sturdy texture but for one piece at the bottom connected only in the corners"

"welding this texture without issues scraping the rust from the long piece beforehand resulting in a sturdy texture but for a small piece at the bottom poorly connected and then having to go in being called by myrthe to help with the kids and letting her sleep despite being already morning"

"good texture with many one pieces and with only one of them weakly connected at the bottom welding now with a lot of rain put and the aspirator protected by a rain jacket"

"being a bit in pain in my nose having stuffed the mask with an old filter yet managing also this texture this time with a poorly connected piece in the bottom and a very poorly connected one on the top left"

"quite strong texture making sure to remove the rust on the edges of a long piece for better welding and with no other issue only thinking of my father involvement with far right terrorism when he was young and possibly still today"

"pretty well connected texture easy to assemble without any bent pieces and easy to weld without any rusted pieces but having to take a break to pee and stay a bit without mask"

"welding after talking to my mother about my father involvement with far right terrorists and his dealing with weapons and reflecting about it making this texture thinking that with my uncle being a gangster i cannot but be the saint of the family and making this texture rather sturdy with only a weakly connected piece on the top left"

"smooth texture but for one piece on the top left lifting itself up while i welded it even though i had secured both side with a dot of weld and generally a texture with some weak connections on the right side but still well connected to the base"

"smooth texture without issues removing the rust from the edges of the long piece in the middle for better welding and sealing with dots all the corners of all the connections to avoid welding then unevenly or with gaps"

"welding this textures now feeling the fumes despite the double filters and nonetheless resulting in quite a sturdy pattern but for one small piece on the top poorly connected and at last hurrying to get my kids from the neighbour where they played for a couple of hours"

"having issues with the gas emission hiring it but still getting welds with bubbles and just going slower to avoid such an issue especially on a single piece poorly connected on the top right also having to hammer down a few overlapping pieces"

"a bit tricky to assemble this texture with many scattered pieces and also again having issues with the porosity having to hold the welding gun perpendicular to the plates despite trying to avoid staying too close to the fumes also having the top right corner poorly connected"

"cleaning the tip of the gun and solving the issue with a porosity doing a rather sturdy texture overall well connected and also with new filters feeling less fumes in my throat"

"good texture but for one small piece on the top poorly connected and still an itchy throat and no way to solving the fumes issue but investing my last money"

"welding for the first time with a helmet provided with a respirator and certainly seeing the improvement avoiding to inhale fumes but feeling quite clumsy and having to get used to it also with a broader view and resulting in an okay texture with only a small piece sticking out on the left"

"a bit of a weak texture with a small piece on the top right and pieces on the bottom left poorly connected also with the gun dirty again blocking the flow of gas and causing porosity"

"cleaning the gun and increasing the gas emission making the weld much more fluent and resulting in a sturdy texture also pausing the air flow of the helmet while assembling it only keeping it on while welding"

"texture almost split in two but for one long piece uniting it at the bottom and overall well connected but for one piece sticking out on the top left"

"quite good texture welded with my new helmet on a sunny sunday with myrthe home with the kids and my new helmet with a air purifier working quite well making a sturdy texture but for a piece poorly connected on the bottom right"

"no issues with this texture just finding a way to put down the ventilator blowing in my helmet and welding everything together but for one piece on the top left poorly connected"

"sturdy texture with some of the small pieces slightly smaller and with the longest not so rusty also preparing a pile of the fifty centimeters ones on my left so as not yo have to bend down to pick them with all the clumsy helmet i now have"

"texture with two weakly connected parts both on the left side and a very sturdy right side deciding to keep up welding on with the other textures"

"well connected texture just starting to feel heavy in my back with all the leaning and the new helmet and respirator around my waist not allowing me so much movement"

"sturdy texture despite the many small pieces which makes me think what would be to weld small cubes on it if they will ever find enough support and at last calling it the day to go help a musician friend to weld a staircase that broke down"

"welding after cleaning up the metal workshop rearranging all the pieces and putting the welder a little too much to the back with the gun cord a bit stuck but managing well the texture with just the top right bending up"

"making a glamorous mistake concerned with my respirator and repeating the exact same texture now having to grind away the welds and recover the top piece for this texture but going rather smooth and anyway learning how to grind the welds to weld aging on them in case i will add the cubes one day to host the mosaics"